


BRASSM (Maestro Brass Master Replica) Stage 1 Wiring

Version 2017November13

Copyright 2009, 2017 JD Sleep

Permission refused for posting/serving this file from any site other than www.generalguitargadgets.com

Trademarks are property of their owners



Stage 1 wiring: Install the pots as shown in this diagram (back view of pots inside the enclosure). Install the switches and the DC jack. Do not install the Input/Output jacks yet. Pop the PCB standoffs into the four corner holes of the PCB, peel and place so that the standoffs are installed. Wire the foot switch and LED as shown above.