


BRASSM (Maestro Brass Master Replica) Stage 4 Wiring

Version 2017November13

Copyright 2009, 2017 JD Sleep

Permission refused for posting/serving this file from any site other than www.generalguitargadgets.com

Trademarks are property of their owners



Stage 4 wiring: Install the input and output jacks and wire them to the bypass foot switch as shown here. Wire Pad "B" PCB board ground to the input jack. Install the battery snap as shown.